




Log of Borehole: MW-4

Logged by:

Client: Washington Department of Ecology Ecology PM: Bill Fees

SUBSURFACE PROFILE				SAMPLE				Well Completion Details
feet (bgs)	feet (MSL)	Symbol	Description	Number	Type	N-Value	Recovery	
-3								 <p>concrete</p> <p>schedule 40 PVC riser</p> <p>3/8" bentonite holeplug</p> <p>steel cover</p>
-1	1218.1		Ground Surface					
1	0.0		SILT, ML, dark brown, loose to soft, non-plastic					
3								
5								
7								
9								
11	1207.1							
13	11.0		Silty GRAVEL with trace to some fine sand, GP-GM, dry, gravels are fine subrounded to subangular.					
15								
17								
19								
21								

Hole Size:

Sheet: 1 of 2

Drill Date: 10/31/00